

## Oak Grove Elementary School

### Lead Tests - Oak Grove Elementary School - Main Building - # 20480800

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20480800-001BF	20480800-001BF22A	North Side of Kitchen Men's Restroom - Sink (Left)	4/10/2019	Passed with 0.00394	None.
2	20480800-002BF	20480800-002BF22A	North Side of Kitchen Men's Restroom - Sink (Right)	4/10/2019	Passed with 0.00523	None.
3	20480800-003BF	20480800-003BF22A	North Side of Kitchen Women's Restroom - Sink (Left)	4/10/2019	Passed with 0.00167	None.
4	20480800-004BF	20480800-004BF22A	North Side of Kitchen Women's Restroom - Sink (Right)	4/10/2019	Passed with 0.00191	None.
5	20480800-005DW	20480800-005DW22A	North Side of Kitchen - Drinking Fountain (Outside)	6/20/2018	Passed with 0.00516	None.
6	20480800-006DW	20480800-006DW22A	East Side of Kitchen - Portable Drinking Fountain (Outside)	7/21/2016	Passed with 0.00955	None.
7	20480800-007BF	20480800-007BF22A	Inside Kitchen Unisex Restroom (East) - Sink	12/27/2019	Passed with 0.00785	None.
8	20480800-008KF	20480800-008KF22A	Kitchen - Sink (Food Prep - Triple Sink)	7/21/2016	Passed with 0.00513	None.
9	20480800-009KF	20480800-009KF22A	Kitchen - Sink (Food Prep - Island)	7/21/2016	Passed with 0.000509	None.
10	20480800-010KF	20480800-010KF22A	Kitchen - Sink (Pre-rinse/Dishwasher)	4/10/2019	Passed with 0.000756	None.
11	20480800-011OT	20480800-011OT22A	Office C - Utility Sink	4/10/2019	Passed with 0.00107	New sink installed in Aug. 2021.
12	20480800-012DW	20480800-012DW22A	Cafeteria - Drinking Fountain	7/21/2016	Passed with 0.00238	This drinking fountain has a sediment filter on it.
13	20480800-013WB	20480800-013WB22A	Cafeteria - Bottle Filler	7/21/2016	Passed with 0.000718	This drinking fountain has a sediment filter on it.
14	20480800-014NS	20480800-014NS22A	Health Room - Sink	7/21/2016	Passed with 0.00305	None.
15	20480800-015BF	20480800-015BF22A	Health Room - Unisex Restroom - Sink	4/10/2019	Passed with 0.00415	None.
16	20480800-016BF	20480800-016BF22A	Staff Work Room - Unisex Restroom - Sink	4/10/2019	Passed with 0.00138	None.
17	20480800-017SF	20480800-017SF22A	Staff Break Room - Sink	7/21/2016	Passed with 0.000633	None.
18	20480800-018SF	20480800-018SF22A	Staff Break Room - Insta Hot	7/21/2016	Passed with 0.000144	None.
19	20480800-019DW	20480800-019DW22A	Multipurpose Room - Drinking Fountain	3/9/2020	Passed with 0.000554	None.
20	20480800-020CF	20480800-020CF22A	Multipurpose Room - Sink	4/10/2019	Passed with 0.00250	None.
21	20480800-021OT	20480800-021OT22A	South of Office Behind Sliding Door - Sink	7/21/2016	Passed with 0.00231	None.
22	20480800-022BF	20480800-022BF22A	Girl's Restroom Near Multipurpose Room - Sink (Left)	4/10/2019	Passed with 0.00317	None.
23	20480800-023BF	20480800-023BF22A	Girl's Restroom Near Multipurpose Room - Sink (Right)	4/10/2019	Passed with 0.00289	None.
24	20480800-024BF	20480800-024BF22A	Boy's Restroom Near Multipurpose Room - Sink (Left)	4/11/2019	Passed with 0.00346	None.
25	20480800-025BF	20480800-025BF22A	Boy's Restroom Near Multipurpose Room - Sink (Right)	4/10/2019	Passed with 0.00358	None.
26	20480800-026DW	20480800-026DW22A	Gym Entrance - Drinking Fountain (Upper)	6/20/2018	Passed with 0.000631	None.
27	20480800-027DW	20480800-027DW22A	Gym Entrance - Drinking Fountain (Lower)	7/21/2016	Passed with 0.00160	None.
28	20480800-028BF	20480800-028BF22A	Media Center Unisex Restroom - Sink	4/10/2019	Passed with 0.00281	None.
29	20480800-029BF	20480800-029BF22A	Near Room 1 Men's Restroom - Sink (1)	12/27/2019	Passed with 0.00300	None.
30	20480800-030BF	20480800-030BF22A	Near Room 1 Men's Restroom - Sink (2)	4/10/2019	Passed with 0.00328	None.
31	20480800-031BF	20480800-031BF22A	Near Room 1 Men's Restroom - Sink (3)	4/10/2019	Passed with 0.00252	None.
32	20480800-032BF	20480800-032BF22A	Near Room 1 Women's Restroom - Sink (1)	4/10/2019	Passed with 0.00216	None.
33	20480800-033BF	20480800-033BF22A	Near Room 1 Women's Restroom - Sink (2)	4/10/2019	Passed with 0.00356	None.
34	20480800-034BF	20480800-034BF22A	Near Room 1 Women's Restroom - Sink (3)	4/10/2019	Passed with 0.00403	None.
35	20480800-035DW	20480800-035DW22A	Near Room 1 / Women's Restroom - Drinking Fountain	7/21/2016	Passed with 0.00502	None.
36	20480800-036DW	20480800-036DW22A	Room 1 - Drinking Fountain	3/9/2020	Passed with 0.00118	None.
37	20480800-037CF	20480800-037CF22A	Room 1 - Sink	4/10/2019	Passed with 0.00258	None.
38	20480800-038DW	20480800-038DW22A	Room 2 - Drinking Fountain	7/21/2016	Passed with 0.00247	None.
39	20480800-039CF	20480800-039CF22A	Room 2 - Sink	4/10/2019	Passed with 0.00210	None.
40	20480800-040DW	20480800-040DW22A	Room 3 - Drinking Fountain	7/21/2016	Passed with 0.00419	None.
41	20480800-041CF	20480800-041CF22A	Room 3 - Sink	4/10/2019	Passed with 0.00406	None.
42	20480800-042DW	20480800-042DW22A	Room 4 - Drinking Fountain	7/21/2016	Passed with 0.00169	None.
43	20480800-043CF	20480800-043CF22A	Room 4 - Sink	4/10/2019	Passed with 0.00239	None.
44	20480800-044DW	20480800-044DW22A	Room 6 - Drinking Fountain	7/21/2016	Passed with 0.00563	None.
45	20480800-045CF	20480800-045CF22A	Room 6 - Sink	4/10/2019	Passed with 0.00515	None.
46	20480800-046BF	20480800-046BF22A	Outside Room 6 Staff Unisex Restroom - Sink	4/10/2019	Passed with 0.000931	None.
47	20480800-047DW	20480800-047DW22A	Room 7 - Drinking Fountain	7/21/2016	Passed with 0.00428	None.
48	20480800-048CF	20480800-048CF22A	Room 7 - Sink	4/10/2019	Passed with 0.00161	None.
49	20480800-049DW	20480800-049DW22A	Room 8 - Drinking Fountain	6/20/2018	Passed with 0.00120	None.
50	20480800-050CF	20480800-050CF22A	Room 8 - Sink	4/10/2019	Passed with 0.00134	None.
51	20480800-051DW	20480800-051DW22A	Room 9 - Drinking Fountain	3/9/2020	Passed with 0.000480	None.
52	20480800-052CF	20480800-052CF22A	Room 9 - Sink	4/10/2019	Passed with 0.00124	None.
53	20480800-053DW	20480800-053DW22A	Room 10 - Drinking Fountain	7/21/2016	Passed with 0.00283	None.
54	20480800-054CF	20480800-054CF22A	Room 10 - Sink	4/10/2019	Passed with 0.00118	None.
55	20480800-055BF	20480800-055BF22A	Near Room 10 Girl's Restroom - Sink (Left)	4/10/2019	Passed with 0.00273	None.
56	20480800-056BF	20480800-056BF22A	Near Room 10 Girl's Restroom - Sink (Right)	4/10/2019	Passed with 0.00347	None.
57	20480800-057BF	20480800-057BF22A	Near Room 10 Boy's Restroom - Sink (Left)	4/10/2019	Passed with 0.00348	None.
58	20480800-058BF	20480800-058BF22A	Near Room 10 Boy's Restroom - Sink (Right)	4/10/2019	Passed with 0.00379	None.
59	N/A	N/A	Inside Kitchen Unisex Restroom (West) - Sink	N/A	N/A	"Non-Potable Water" Sign Installed 23 Jan 2020.
60	N/A	N/A	Kitchen - Sink (Hand Wash)	N/A	N/A	"Non-Potable Water" Sign Installed 23 Jan 2020.

### Lead Tests - Oak Grove Elementary School - North Wing - # 20480801

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
---	--------------	-------------	---------------	-------------	-------------------	---------

1	20480801-001DW	20480801-001DW22A	Room 18 - Drinking Fountain	7/21/2016	Passed with 0.000514	None.
2	20480801-002CF	20480801-002CF22A	Room 18 - Sink	4/10/2019	Passed with 0.00152	None.
3	20480801-003DW	20480801-003DW22A	Room 19 - Drinking Fountain	7/21/2016	Passed with 0.000380	None.
4	20480801-004CF	20480801-004CF22A	Room 19 - Sink	4/10/2019	Passed with 0.00181	None.
5	20480801-005DW	20480801-005DW22A	Room 20 - Drinking Fountain	7/21/2016	Passed with 0.000397	None.
6	20480801-006CF	20480801-006CF22A	Room 20 - Sink	4/10/2019	Passed with 0.000860	None.
7	20480801-007DW	20480801-007DW22A	Room 21 - Drinking Fountain	7/21/2016	Passed with 0.000472	None.
8	20480801-008CF	20480801-008CF22A	Room 21 - Sink	4/10/2019	Passed with 0.00161	None.
9	20480801-009DW	20480801-009DW22A	Room 22 - Drinking Fountain	6/20/2018	Passed with 0.000229	None.
10	20480801-010CF	20480801-010CF22A	Room 22 - Sink	4/10/2019	Passed with 0.00112	None.
11	20480801-011DW	20480801-011DW22A	Room 23 - Drinking Fountain	7/21/2016	Passed with 0.000300	None.
12	20480801-012CF	20480801-012CF22A	Room 23 - Sink	4/10/2019	Passed with 0.00127	None.
13	20480801-013DW	20480801-013DW22A	Room 24 - Drinking Fountain	7/21/2016	Passed with 0.00247	None.
14	20480801-014CF	20480801-014CF22A	Room 24 - Sink	4/10/2019	Passed with 0.00287	None.
15	20480801-015DW	20480801-015DW22A	Room 25 - Drinking Fountain	7/21/2016	Passed with 0.000301	None.
16	20480801-016CF	20480801-016CF22A	Room 25 - Sink	4/10/2019	Passed with 0.00160	None.
17	20480801-017DW	20480801-017DW22A	Room 26 - Drinking Fountain	3/9/2020	Passed with 0.000378	None.
18	20480801-018CF	20480801-018CF22A	Room 26 - Sink	4/10/2019	Passed with 0.00181	None.
19	20480801-019BF	20480801-019BF22A	Outside Room 26 Boy's Restroom - Sink (1) North	4/10/2019	Passed with 0.00298	None.
20	20480801-020BF	20480801-020BF22A	Outside Room 26 Boy's Restroom - Sink (2)	4/10/2019	Passed with 0.00482	None.
21	20480801-021BF	20480801-021BF22A	Outside Room 26 Boy's Restroom - Sink (3)	4/10/2019	Passed with 0.00473	None.
22	20480801-022BF	20480801-022BF22A	Outside Room 26 Boy's Restroom - Sink (4)	4/10/2019	Passed with 0.00155	None.
23	20480801-023BF	20480801-023BF22A	Outside Room 26 Boy's Restroom - Sink (5)	4/10/2019	Passed with 0.000354	None.
24	20480801-024BF	20480801-024BF22A	Outside Room 26 Boy's Restroom - Sink (6)	4/10/2019	Passed with 0.00456	None.
25	20480801-025BF	20480801-025BF22A	Outside Room 26 Boy's Restroom - Sink (7)	4/10/2019	Passed with 0.00250	None.
26	20480801-026BF	20480801-026BF22A	Outside Room 26 Boy's Restroom - Sink (8)	4/10/2019	Passed with 0.000846	None.
27	20480801-027BF	20480801-027BF22A	Outside Room 26 Boy's Restroom - Sink (9) South	4/10/2019	Passed with 0.00369	None.
28	20480801-028BF	20480801-028BF22A	Outside Room 26 Women's Restroom - Sink (1) North	4/10/2019	Passed with 0.00134	None.
29	20480801-029BF	20480801-029BF22A	Outside Room 26 Women's Restroom - Sink (2)	4/10/2019	Passed with 0.000970	None.
30	20480801-030BF	20480801-030BF22A	Outside Room 26 Women's Restroom - Sink (3)	4/10/2019	Passed with 0.00293	None.
31	20480801-031BF	20480801-031BF22A	Outside Room 26 Women's Restroom - Sink (4)	4/10/2019	Passed with 0.00259	None.
32	20480801-032BF	20480801-032BF22A	Outside Room 26 Women's Restroom - Sink (5)	4/10/2019	Passed with 0.00293	None.
33	20480801-033BF	20480801-033BF22A	Outside Room 26 Women's Restroom - Sink (6)	4/10/2019	Passed with 0.00468	None.
34	20480801-034BF	20480801-034BF22A	Outside Room 26 Women's Restroom - Sink (7)	4/10/2019	Passed with 0.00277	None.
35	20480801-035BF	20480801-035BF22A	Outside Room 26 Women's Restroom - Sink (8)	4/10/2019	Passed with 0.00387	None.
36	20480801-036BF	20480801-036BF22A	Outside Room 26 Women's Restroom - Sink (9) South	4/10/2019	Passed with 0.00409	None.
<b>Lead Tests - Oak Grove Elementary School - West Wing - # 20480802</b>						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20480802-001DW	20480802-001DW22A	Room 14 - Drinking Fountain	7/21/2016	Passed with 0.00107	None.
2	20480802-002CF	20480802-002CF22A	Room 14 - Sink	4/10/2019	Passed with 0.00189	None.
3	20480802-003DW	20480802-003DW22A	Room 15 - Drinking Fountain	7/21/2016	Passed with 0.00230	None.
4	20480802-004CF	20480802-004CF22A	Room 15 - Sink	4/10/2019	Passed with 0.00166	None.
5	20480802-005DW	20480802-005DW22A	Room 16 - Drinking Fountain	7/21/2016	Passed with 0.000679	None.
6	20480802-006CF	20480802-006CF22A	Room 16 - Sink	4/10/2019	Passed with 0.000726	None.
7	20480802-007DW	20480802-007DW22A	Room 17 - Drinking Fountain	7/21/2016	Passed with 0.000920	None.
8	20480802-008CF	20480802-008CF22A	Room 17 - Sink	4/10/2019	Passed with 0.000863	None.
<b>Lead Tests - Oak Grove Elementary School - Central Wing - # 20480803</b>						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20480803-001DW	20480803-001DW22A	Room 11 - Drinking Fountain	7/21/2016	Passed with 0.00435	None.
2	20480803-002CF	20480803-002CF22A	Room 11 - Sink	4/10/2019	Passed with 0.00301	None.
3	20480803-003DW	20480803-003DW22A	Room 12 - Drinking Fountain	7/21/2016	Passed with 0.00463	None.
4	20480803-004CF	20480803-004CF22A	Room 12 - Sink	4/10/2019	Passed with 0.00348	None.
5	20480803-005DW	20480803-005DW22A	Room 13 - Drinking Fountain	7/21/2016	Passed with 0.00466	None.
6	20480803-006CF	20480803-006CF22A	Room 13 - Sink	4/10/2019	Passed with 0.00247	None.
<b>Lead Tests - Oak Grove Elementary School - Modular - # 20480804</b>						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20480804-001NS	20480804-001NS22A	La Clinica Exam Room # 1 - Sink	7/21/2016	Passed with 0.00184	None.
2	20480804-002NS	20480804-002NS22A	La Clinica Exam Room # 2 - Sink	7/21/2016	Passed with 0.00120	None.
3	20480804-003NS	20480804-003NS22A	La Clinica Lab Room - Sink	7/21/2016	Passed with 0.00131	None.
4	20480804-004BF	20480804-004BF22A	La Clinica Restroom - Sink	4/10/2019	Passed with 0.000937	None.

= Fixture Where Water Has The Potential of Being Consumed (All of These Will Be Tested When Testing The Whole School)

\*ODE's required action level is 15 parts per billion (PPB)

\*The E.P.A.'s recommended action level for lead in schools is 0.020. Oregon's action level for schools changed to 0.015 in 2019 in accordance with OAR 333-061-0400. In 2021, ODE changed the unit of measurement for reporting to parts per billion (PPB)

\*The E.P.A. action level for copper is 1.30

\*Lead test results will be posted on the MSD/Facilities website within 5 days minus the school map for security purposes.