

## Washington Elementary School

### Lead Tests - Washington Elementary School - Main Building - # 20481200

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481200-001NS	20481200-001NS26A	Health Room - Sink	7/11/2018	Passed with 0.00123	None.
2	20481200-002BF	20481200-002BF26A	Health Room Unisex Restroom - Sink	4/5/2019	Passed with 0.00293	None.
3	20481200-003BF	20481200-003BF26A	1st Floor Boy's Restroom Across From Room 3 - Sink (Left)	4/5/2019	Passed with 0.00438	None.
4	20481200-004BF	20481200-004BF26A	1st Floor Boy's Restroom Across From Room 3 - Sink (Center)	4/5/2019	Passed with 0.00397	None.
5	20481200-005BF	20481200-005BF26A	1st Floor Boy's Restroom Across From Room 3 - Sink (Right)	4/5/2019	Passed with 0.00344	None.
6	20481200-006DW	20481200-006DW26A	1st Floor Outside Boy's Restroom - Drinking Fountain (Left)	3/13/2020	Passed with 0.000581	None.
7	20481200-007DW	20481200-007DW26A	1st Floor Outside Boy's Restroom - Drinking Fountain (Right)	7/11/2018	Passed with 0.00209	None.
8	20481200-008BF	20481200-008BF26A	1st Floor Girl's Restroom Across From Office - Sink (Left)	4/5/2019	Passed with 0.00368	None.
9	20481200-009BF	20481200-009BF26A	1st Floor Girl's Restroom Across From Office - Sink (Center)	4/5/2019	Passed with 0.00277	None.
10	20481200-010BF	20481200-010BF26A	1st Floor Girl's Restroom Across From Office - Sink (Right)	4/5/2019	Passed with 0.00172	None.
11	20481200-011DW	20481200-011DW26A	1st Floor By Office/Trophy Case - Drinking Fountain (Left)	7/11/2018	Passed with 0.00197	None.
12	20481200-012DW	20481200-012DW26A	1st Floor By Office/Trophy Case - Drinking Fountain (Right)	7/11/2018	Passed with 0.000696	None.
13	20481200-013BF	20481200-013BF26A	1st Floor Staff Men's Restroom Near Office - Sink	4/5/2019	Passed with 0.00601	None.
14	20481200-014BF	20481200-014BF26A	1st Floor Staff Women's Restroom Near Office - Sink	4/5/2019	Passed with 0.00107	None.
15	20481200-015KF	20481200-015KF26A	Kitchen - Sink (Food Prep - South Wall)	3/27/2019	Passed with 0.000155	None.
16	20481200-016KF	20481200-016KF26A	Kitchen - Sink (Hand/Eye Wash - South Wall)	4/5/2019	Passed with 0.00276	None.
17	20481200-017KF	20481200-017KF26A	Kitchen - Sink (Triple Sink - South Wall)	7/11/2018	Passed with 0.00763	None.
18	20481200-018KF	20481200-018KF26A	Kitchen - Sink (Pre-rinse/Dishwasher - Sprayer Only)	4/5/2019	Passed with 0.000751	None.
19	20481200-019KF	20481200-019KF26A	Kitchen - Sink (Hand Wash/Serving Line)	4/5/2019	Passed with 0.000568	None.
20	20481200-020BF	20481200-020BF26A	Kitchen Unisex Restroom - Sink	4/5/2019	Passed with 0.00400	None.
21	20481200-021DW	20481200-021DW26A	Playground - Drinking Fountain (Outside Cafeteria)- Upper	5/5/2020	Passed with 0.000412	None.
22	20481200-022DW	20481200-022DW26A	Playground - Drinking Fountain (Outside Cafeteria)- Lower	5/5/2020	Passed with 0.000602	None.
N/A	N/A	N/A	Outside Portable - Drinking Fountain (Fixture 1)	7/11/2018	Passed with 0.000797	This fountain is no longer in use.
N/A	N/A	N/A	Outside Portable - Drinking Fountain (Fixture 2)	7/11/2018	Passed with 0.00127	This fountain is no longer in use.
N/A	N/A	N/A	Outside Portable - Drinking Fountain (Fixture 3)	7/11/2018	Passed with 0.000893	This fountain is no longer in use.
N/A	N/A	N/A	Outside Portable - Drinking Fountain (Fixture 4)	7/11/2018	Passed with 0.00105	This fountain is no longer in use.
N/A	N/A	N/A	Outside Portable - Drinking Fountain (Fixture 5)	7/11/2018	Passed with 0.000855	This fountain is no longer in use.
N/A	N/A	N/A	Outside Portable - Drinking Fountain (Fixture 6)	7/11/2018	Passed with 0.00162	This fountain is no longer in use.
23	20481200-023DW	20481200-023DW26A	La Clinica - Exam Room # 1 - Drinking Fountain	7/11/2018	Passed with 0.00199	None.
24	20481200-024NS	20481200-024NS26A	La Clinica - Exam Room # 1 - Sink	3/27/2019	Passed with 0.000725	None.
25	20481200-025NS	20481200-025NS26A	La Clinica - Exam Room # 2 - Sink	7/11/2018	Passed with 0.00249	None.
26	20481200-026NS	20481200-026NS26A	La Clinica - Hand Wash Near Outside Restroom - Sink	4/5/2019	Passed with 0.000964	None.
27	20481200-027DW	20481200-027DW26A	Room 1 - Drinking Fountain	3/13/2020	Passed with 0.000671	None.
28	20481200-028CF	20481200-028CF26A	Room 1 - Sink	7/11/2018	Passed with 0.00752	None.
N/A	N/A	N/A	Room 2 - Drinking Fountain	4/9/2008	Passed with None Detected	This drinking fountain was removed at the school's request.
29	20481200-029CF	20481200-029CF26A	Room 2 - Sink	7/11/2018	Passed with 0.00698	None.
30	20481200-030DW	20481200-030DW26A	Room 3 - Drinking Fountain	7/11/2018	Passed with 0.00253	None.
31	20481200-031CF	20481200-031CF26A	Room 3 - Sink	4/5/2019	Passed with 0.00361	None.
32	20481200-032DW	20481200-032DW26A	Room 5 - Drinking Fountain	7/11/2018	Passed with 0.00154	None.
33	20481200-033CF	20481200-033CF26A	Room 5 - Sink	4/5/2019	Passed with 0.00248	None.
34	20481200-034DW	20481200-034DW26A	Room 6 - Drinking Fountain	7/11/2018	Passed with 0.00160	None.
35	20481200-035CF	20481200-035CF26A	Room 6 - Sink	4/5/2019	Passed with 0.00290	None.
36	20481200-036DW	20481200-036DW26A	Room 7 - Drinking Fountain	7/11/2018	Passed with 0.00229	This drinking fountain has a lead filter on it.
37	20481200-037CF	20481200-037CF26A	Room 7 - Sink	12/2/2019	Passed with 0.000629	None.
38	20481200-038DW	20481200-038DW26A	Room 8 - Drinking Fountain	7/11/2018	Passed with 0.00214	This drinking fountain has a lead filter on it.
39	20481200-039CF	20481200-039CF26A	Room 8 - Sink	4/5/2019	Passed with 0.00748	None.
40	20481200-040SF	20481200-040SF26A	Media Center Work Room - Sink	4/5/2019	Passed with 0.00152	None.
41	20481200-041BF	20481200-041BF26A	Media Center Staff Only Unisex Restroom - Sink	4/5/2019	Passed with 0.00603	None.
42	20481200-042DW	20481200-042DW26A	Room 9 - Drinking Fountain	7/11/2018	Passed with 0.00184	None.
43	20481200-043CF	20481200-043CF26A	Room 9 - Sink	4/5/2019	Passed with 0.00348	None.
44	20481200-044BF	20481200-044BF26A	Room 9 Unisex Restroom (Left) - Sink	4/5/2019	Passed with 0.00777	None.
45	20481200-045BF	20481200-045BF26A	Room 9 Unisex Restroom (Right) - Sink	4/5/2019	Passed with 0.00340	None.
46	20481200-046BF	20481200-046BF26A	Boy's Restroom Outside Room 9 - Sink (Left)	4/5/2019	Passed with 0.00678	None.
47	20481200-047BF	20481200-047BF26A	Boy's Restroom Outside Room 9 - Sink (Center)	4/5/2019	Passed with 0.00723	None.
48	20481200-048BF	20481200-048BF26A	Boy's Restroom Outside Room 9 - Sink (Right)	4/5/2019	Passed with 0.00721	None.
49	20481200-049DW	20481200-049DW26A	Room 10 - Drinking Fountain	3/13/2020	Passed with 0.000578	None.
50	20481200-050CF	20481200-050CF26A	Room 10 - Sink	4/5/2019	Passed with 0.000902	None.
51	20481200-051BF	20481200-051BF26A	Room 10 Unisex Restroom - Sink	4/5/2019	Passed with 0.000590	None.
52	20481200-052DW	20481200-052DW26A	1st Floor Outside Room 11 - Drinking Fountain (Left)	7/11/2018	Passed with 0.000188	None.
53	20481200-053DW	20481200-053DW26A	1st Floor Outside Room 11 - Drinking Fountain (Right)	7/11/2018	Passed with 0.000265	None.
54	20481200-054DW	20481200-054DW26A	Room 11 - Drinking Fountain	7/11/2018	Passed with 0.000558	None.
55	20481200-055CF	20481200-055CF26A	Room 11 - Sink	4/5/2019	Passed with 0.000453	None.
56	20481200-056BF	20481200-056BF26A	Room 11 Unisex Restroom - Sink	4/5/2019	Passed with 0.000190	None.

57	20481200-057DW	20481200-057DW26A	Room 12 - Drinking Fountain	7/11/2018	Passed with 0.00578	None.
58	20481200-058CF	20481200-058CF26A	Room 12 - Sink	4/5/2019	Passed with 0.00852	None.
59	20481200-059DW	20481200-059DW26A	Staff Break Room (Room 13) - Drinking Fountain	7/11/2018	Passed with 0.00378	None.
60	20481200-060SF	20481200-060SF26A	Staff Break Room (Room 13) - Sink	3/27/2019	Passed with 0.000230	None.
61	20481200-061CF	20481200-061CF26A	Room 14 - Sink	4/5/2019	Passed with 0.00149	None.
62	20481200-062DW	20481200-062DW26A	Room 20 - Drinking Fountain	7/11/2018	Passed with 0.000817	None.
63	20481200-063CF	20481200-063CF26A	Room 20 - Sink	4/5/2019	Passed with 0.00319	None.
64	20481200-064DW	20481200-064DW26A	Room 21 - Drinking Fountain	7/11/2018	Passed with 0.00133	None.
65	20481200-065CF	20481200-065CF26A	Room 21 - Sink	4/5/2019	Passed with 0.00285	None.
N/A	N/A	N/A	Room 21A - Sink (Left - Faucet) (Hot)	TBD	N/A	"Non-Potable Water" Sign Installed 16 Dec 2019.
66	20481200-066CF	20481200-066CF26A	Room 21A - Sink (Right - Faucet) (Cold)	4/5/2019	Passed with 0.00456	None.
67	20481200-067DW	20481200-067DW26A	Room 22 - Drinking Fountain	7/11/2018	Passed with 0.000897	None.
68	20481200-068CF	20481200-068CF26A	Room 22 - Sink	4/5/2019	Passed with 0.00485	None.
69	20481200-069DW	20481200-069DW26A	2nd Floor Outside Boy's Restroom/22 - Drinking Fountain (Left)	7/11/2018	Passed with 0.00177	None.
70	20481200-070DW	20481200-070DW26A	2nd Floor Outside Boy's Restroom/22 - Drinking Fountain (Right)	7/11/2018	Passed with 0.00256	None.
71	20481200-071BF	20481200-071BF26A	2nd Floor Boy's Restroom Across From Room 22 - Sink (Left)	4/5/2019	Passed with 0.00212	None.
72	20481200-072BF	20481200-072BF26A	2nd Floor Boy's Restroom Across From Room 22 - Sink (Center)	4/5/2019	Passed with 0.000806	None.
73	20481200-073BF	20481200-073BF26A	2nd Floor Boy's Restroom Across From Room 22 - Sink (Right)	4/5/2019	Passed with 0.000936	None.
74	20481200-074DW	20481200-074DW26A	Room 23 - Drinking Fountain	3/13/2020	Passed with 0.00294	None.
75	20481200-075CF	20481200-075CF26A	Room 23 - Sink	12/2/2019	Passed with 0.000279	None.
76	20481200-076BF	20481200-076BF26A	2nd Floor Girl's Restroom Across From Room 23 - Sink (Left)	4/5/2019	Passed with 0.00194	None.
77	20481200-077BF	20481200-077BF26A	2nd Floor Girl's Restroom Across From Room 23 - Sink (Center)	4/5/2019	Passed with 0.00157	None.
78	20481200-078BF	20481200-078BF26A	2nd Floor Girl's Restroom Across From Room 23 - Sink (Right)	4/5/2019	Passed with 0.00106	None.
79	20481200-079DW	20481200-079DW26A	2nd Floor Outside Room 23-A - Drinking Fountain (Left)	7/11/2018	Passed with 0.00284	None.
80	20481200-080DW	20481200-080DW26A	2nd Floor Outside Room 23-A - Drinking Fountain (Right)	7/11/2018	Passed with 0.00137	None.
81	20481200-081DW	20481200-081DW26A	Room 24 - Drinking Fountain	7/11/2018	Passed with 0.00114	None.
82	20481200-082CF	20481200-082CF26A	Room 24 - Sink	4/5/2019	Passed with 0.000429	None.
83	20481200-083DW	20481200-083DW26A	Room 25 - Drinking Fountain	7/11/2018	Passed with 0.00156	None.
84	20481200-084CF	20481200-084CF26A	Room 25 - Sink	4/5/2019	Passed with 0.000657	None.
85	20481200-085DW	20481200-085DW26A	Room 26 - Drinking Fountain	7/11/2018	Passed with 0.00245	This drinking fountain has a lead filter on it.
86	20481200-086CF	20481200-086CF26A	Room 26 - Sink	12/2/2019	Passed with 0.00108	None.
87	20481200-087DW	20481200-087DW26A	Room 27 - Drinking Fountain	7/11/2018	Passed with 0.00337	None.
88	20481200-088CF	20481200-088CF26A	Room 27 - Sink	4/5/2019	Passed with 0.00344	None.
89	20481200-089DW	20481200-089DW26A	2nd Floor Hallway Outside Room 27 - Drinking Fountain (Left)	7/11/2018	Passed with 0.000618	This drinking fountain has a lead filter on it.
90	20481200-090DW	20481200-090DW26A	2nd Floor Hallway Outside Room 27 - Drinking Fountain (Right)	7/11/2018	Passed with 0.00573	This drinking fountain has a lead filter on it.
91	20481200-091DW	20481200-091DW26A	Room 28 - Drinking Fountain	7/11/2018	Passed with 0.00718	None.
92	20481200-092CF	20481200-092CF26A	Room 28 - Sink	4/5/2019	Passed with 0.00607	None.
93	20481200-093DW	20481200-093DW26A	Room 29 - Drinking Fountain	7/11/2018	Passed with 0.00230	This drinking fountain has a lead filter on it.
94	20481200-094CF	20481200-094CF26A	Room 29 - Sink	4/5/2019	Passed with 0.00645	None.
95	20481200-095BF	20481200-095BF26A	Girl's Restroom Across From Room 29 - Sink (Left)	4/5/2019	Passed with 0.00176	None.
96	20481200-096BF	20481200-096BF26A	Girl's Restroom Across From Room 29 - Sink (Center)	4/5/2019	Passed with 0.00737	None.
97	20481200-097BF	20481200-097BF26A	Girl's Restroom Across From Room 29 - Sink (Right)	4/5/2019	Passed with 0.00170	None.
98	20481200-098DW	20481200-098DW26A	Room 30 - Drinking Fountain	7/11/2018	Passed with 0.00470	None.
99	20481200-099CF	20481200-099CF26A	Room 30 - Sink	4/5/2019	Passed with 0.00708	None.
100	20481200-100DW	20481200-100DW26A	Room 31 - Drinking Fountain	7/11/2018	Passed with 0.00668	None.
101	20481200-101CF	20481200-101CF26A	Room 31 - Sink	4/5/2019	Passed with 0.00818	None.

\*None Detected (ND) = .005 Or Less

None = Fixture Where Water Has The Potential of Being Consumed (All of These Will Be Tested When Testing The Whole School)

\*ODE's required action level is 15 parts per billion (PPB)

\*The E.P.A.'s recommended action level for lead in schools is 0.020. Oregon's action level for schools changed to 0.015 in 2019 in accordance with OAR 333-061-0400. In 2021, ODE changed the unit of measurement for reporting to parts per billion (PPB)

\*The E.P.A. action level for copper is 1.30

\*Lead test results will be posted on the MSD/Facilities website within 5 days minus the school map for security purposes.