

North High School

Lead Tests - North Medford High Main Building - # 20481700

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481700-001DW	20481700-001DW26A	(A) Main Office - Bottle Filler	6/18/2018	Passed with 0.000114	None.
2	20481700-002DW	20481700-002DW26A	(A) Main Office - Drinking Fountain	6/18/2018	Passed with 0.000142	None.
3	20481700-003SF	20481700-003SF26A	(A) Tornado Conference Room - Sink	6/18/2018	Passed with 0.000832	None.
4	20481700-004DW	20481700-004DW26A	(A) Courtyard Behind Main Office - Drinking Fountain (Upper)	5/6/2020	Passed with 0.00274	None.
5	20481700-005DW	20481700-005DW26A	(A) Courtyard Behind Main Office - Drinking Fountain (Lower)	6/18/2018	Passed with 0.000188	None.
6	20481700-006BF	20481700-006BF26A	(A) West Men's Rest Room - Sink	5/8/2019	Passed with 0.000103	None.
7	20481700-007BF	20481700-007BF26A	(A) West Women's Rest Room - Sink (Left)	5/8/2019	Passed with 0.00163	None.
8	20481700-008BF	20481700-008BF26A	(A) West Women's Rest Room - Sink (Right)	5/8/2019	Passed with 0.00277	None.
9	20481700-009BF	20481700-009BF26A	(A) Health Room Unisex Rest Room - Sink	5/8/2019	Passed with 0.00102	None.
10	20481700-010BF	20481700-010BF26A	(A) South Men's Rest Room - Sink	5/8/2019	Passed with 0.00145	None.
11	20481700-011BF	20481700-011BF26A	(A) South Women's Rest Room - Sink	5/8/2019	Passed with 0.00203	None.
12	20481700-012BF	20481700-012BF26A	(A) East Men's Rest Room - Sink	5/8/2019	Passed with 0.00145	None.
13	20481700-013BF	20481700-013BF26A	(A) East Women's Rest Room - Sink	5/8/2019	Passed with 0.00153	None.
14	20481700-014SF	20481700-014SF26A	(A) Staff Break Room - Sink	6/18/2018	Passed with None Detected	None.
15	20481700-015IM	20481700-015IM26A	(A) Staff Break Room - Ice Maker	6/18/2018	Passed with 0.00234	None.

Lead Tests - North Medford High Fine Arts Building - # 20481701

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481701-001DW	20481701-001DW26A	FA - Lobby - Drinking Fountain	6/18/2018	Passed with 0.000810	None.
2	20481701-002BF	20481701-002BF26A	FA - Lobby - Men's Restroom - Sink (Left)	5/8/2019	Passed with 0.000818	None.
3	20481701-003BF	20481701-003BF26A	FA - Lobby - Men's Restroom - Sink (Right)	5/8/2019	Passed with 0.000417	None.
4	20481701-004BF	20481701-004BF26A	FA - Lobby - Women's Restroom - Sink (Left)	5/8/2019	Passed with 0.000948	None.
5	20481701-005BF	20481701-005BF26A	FA - Lobby - Women's Restroom - Sink (Right)	5/8/2019	Passed with 0.000423	None.
6	20481701-006BF	20481701-006BF26A	FA - Lobby - Unisex Restroom - Sink	5/8/2019	Passed with 0.00216	None.
7	20481701-007CF	20481701-007CF26A	IDF Room Next to FA-3 - Sink	8/20/2019	Passed with 0.000458	None.
8	20481701-008OT	20481701-008OT26A	IDF Room Next to FA-3 - Spray Nozzle	9/10/2019	Passed with 0.00522	None.
9	20481701-009DW	20481701-009DW26A	Outside FA-3 - Drinking Fountain	6/18/2018	Passed with 0.000890	None.
10	20481701-010BF	20481701-010BF26A	Outside FA-3 - Unisex Restroom - Sink	5/8/2019	Passed with 0.00535	None.
11	20481701-011CF	20481701-011CF26A	FA-5 - Sink (South Wall)	5/8/2019	Passed with 0.00132	None.
12	20481701-012CF	20481701-012CF26A	FA-5 - Sink (North Wall)	5/8/2019	Passed with 0.00106	None.
N/A	N/A	N/A	FA-5 - North Wall Trough Sink (Fixture 1)	N/A	N/A	Technical education classroom (Pottery) - Fixtures are not operational.
N/A	N/A	N/A	FA-5 - North Wall Trough Sink (Fixture 2)	N/A	N/A	Technical education classroom (Pottery) - Fixtures are not operational.
N/A	N/A	N/A	FA-5 - North Wall Trough Sink (Fixture 3)	N/A	N/A	Technical education classroom (Pottery) - Fixtures are not operational.
N/A	N/A	N/A	FA-5 - North Wall Trough Sink (Fixture 4)	N/A	N/A	Technical education classroom (Pottery) - Fixtures are not operational.
N/A	N/A	N/A	FA-5 - North Wall Trough Sink (Fixture 5)	N/A	N/A	Technical education classroom (Pottery) - Fixtures are not operational.
N/A	N/A	N/A	FA-5 - North Wall Trough Sink (Fixture 6)	N/A	N/A	Technical education classroom (Pottery) - Fixtures are not operational.
13	20481701-013CF	20481701-013CF26A	FA-5 - Kiln Area - Sink (Left Fixture)	5/8/2019	Passed with 0.000896	None.
14	20481701-014CF	20481701-014CF26A	FA-5 - Kiln Area - Sink (Right Fixture)	5/8/2019	Passed with 0.00272	None.
15	20481701-015CF	20481701-015CF26A	FA-6 - Island Sink (1)	5/8/2019	Passed with 0.00186	None.
16	20481701-016CF	20481701-016CF26A	FA-6 - Island Sink (2)	5/8/2019	Passed with 0.000730	None.
17	20481701-017CF	20481701-017CF26A	FA-6 - Island Sink (3)	5/8/2019	Passed with 0.000655	None.
18	20481701-018CF	20481701-018CF26A	FA-6 - Island Sink (4)	5/8/2019	Passed with 0.00168	None.
19	20481701-019CF	20481701-019CF26A	FA-6 - Sink (South Wall)	5/8/2019	Passed with 0.00689	None.
20	20481701-020BF	20481701-020BF26A	FA-7 - Entrance - Men's Restroom - Sink	8/20/2019	Passed with 0.00643	None.
21	20481701-021BF	20481701-021BF26A	FA-7 - Entrance - Women's Restroom - Sink	5/8/2019	Passed with 0.00287	None.
22	20481701-022DW	20481701-022DW26A	FA-7 - Entrance - Drinking Fountain	6/18/2018	Passed with 0.00108	This has a lead filter on it.
23	20481701-023CF	20481701-023CF26A	FA-8 - Sink	5/8/2019	Passed with 0.00664	None.
24	20481701-024OT	20481701-024OT26A	FA - Outside Dressing Rooms - Paint Sink	8/20/2019	Passed with 0.000898	None.
25	20481701-025CF	20481701-025CF26A	FA - Girl's Dressing Room - Sink	8/28/2019	Passed with 0.000747	None.
26	20481701-026BF	20481701-026BF26A	FA - Girl's Dressing Room Restroom - Sink	5/8/2019	Passed with 0.00116	None.
27	20481701-027CF	20481701-027CF26A	FA - Boy's Dressing Room - Sink	5/8/2019	Passed with 0.00279	None.
28	20481701-028BF	20481701-028BF26A	FA - Boy's Dressing Room Restroom - Sink	5/8/2019	Passed with 0.00264	None.

Lead Tests - North Medford High Cafeteria - # 20481702

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481702-001KF	20481702-001KF26A	Dish Washer (DW) Area - East Wall - Pre-rinse Sink	5/8/2019	Passed with 0.000658	None.
2	20481702-002KF	20481702-002KF26A	DW Area - East Wall - Pre-rinse Spray Nozzle (Left)	5/8/2019	Passed with 0.00995	None.
3	20481702-003KF	20481702-003KF26A	DW Area - East Wall - Pre-rinse Spray Nozzle (Right)	5/8/2019	Passed with 0.00292	None.
4	20481702-004KF	20481702-004KF26A	DW Area - West Wall - Hand Wash Sink (South West Corner)	5/8/2019	Passed with 0.000367	None.
5	20481702-005KF	20481702-005KF26A	DW Area - West Wall - Pre-rinse Sink (Left)	5/8/2019	Passed with 0.00412	None.
6	20481702-006KF	20481702-006KF26A	DW Area - West Wall - Spray Nozzle (Left)	5/8/2019	Passed with 0.000852	None.
7	20481702-007KF	20481702-007KF26A	DW Area - West Wall - Pre-rinse Sink (Right)	5/8/2019	Passed with 0.00179	None.
8	20481702-008BF	20481702-008BF26A	Kitchen - Men's Restroom - Sink	5/8/2019	Passed with 0.000255	None.
9	20481702-009BF	20481702-009BF26A	Kitchen - Women's Restroom - Sink	5/8/2019	Passed with 0.000201	None.

10	20481702-010KF	20481702-010KF26A	Kitchen - East Wall - Hand Wash Sink (Left)	5/8/2019	Passed with 0.00270	None.
11	20481702-011KF	20481702-011KF26A	Kitchen - East Wall - Hand Wash Sink (Right)	5/8/2019	Passed with 0.00200	None.
12	20481702-012KF	20481702-012KF26A	Kitchen - East Wall - Food Prep Sink	6/18/2018	Passed with 0.00153	None.
13	20481702-013KF	20481702-013KF26A	Kitchen - East Island - Hand Wash Sink (Eye Wash)	5/8/2019	Passed with 0.000684	None.
14	20481702-014KF	20481702-014KF26A	Kitchen - East Island - Food Prep - Sink	6/18/2018	Passed with 0.00399	None.
15	20481702-015KF	20481702-015KF26A	Kitchen - North West Wall - Food Prep - Sink	6/18/2018	Passed with 0.00374	None.
16	20481702-016KF	20481702-016KF26A	Kitchen - NW Hand Wash Sink By Hall			Added 09/15/21. Need to test.
17	20481702-017KF	20481702-017KF26A	Kitchen - North East Wall - Food Prep - Sink (Left)	6/18/2018	Passed with 0.00265	None.
18	20481702-018KF	20481702-018KF26A	Kitchen - North East Wall - Food Prep - Sink (Right)	6/18/2018	Passed with 0.00212	None.
19	20481702-019KF	20481702-019KF26A	Kitchen - Small Kettle - Faucet	6/18/2018	Passed with 0.00267	None.
20	20481702-020KF	20481702-020KF26A	Kitchen - Large Kettle - Faucet	6/18/2018	Passed with 0.00154	None.
21	20481702-021KF	20481702-021KF26A	Kitchen - Spray Nozzle To Right of Large Kettle	6/18/2018	Passed with 0.00310	None.
22	20481702-022KF	20481702-022KF26A	Kitchen - Steam Oven (Upper - Filtered)	6/18/2018	Passed with 0.00140	This has a sediment filter on it.
N/A	N/A	N/A	Kitchen - Steam Oven (Upper - Un-filtered)	6/18/2018	Passed with 0.0185	This was discovered to feed condensate. It has no need to be tested.
23	20481702-023KF	20481702-023KF26A	Kitchen - Steam Oven (Lower)	6/18/2018	Passed with 0.00708	None.
24	20481702-024KF	20481702-024KF26A	Kitchen - West Wall - Hand Wash Sink	5/8/2019	Passed with 0.000671	None.
25	20481702-025KF	20481702-025KF26A	Kitchen - Coffee Machine (North West Corner)	6/18/2018	Passed with 0.00948	None.
26	20481702-026KF	20481702-026KF26A	Kitchen - Wok Faucet	6/18/2018	Passed with 0.00102	None.
27	20481702-027KF	20481702-027KF26A	Kitchen - Soda Machine (East)	6/18/2018	Passed with 0.000178	None.
28	20481702-028IM	20481702-028IM26A	Kitchen - Soda Machine Ice Maker (East)	6/18/2018	Passed with None Detected	None.
29	20481702-029KF	20481702-029KF26A	Kitchen - Soda Machine (West)	6/18/2018	Passed with 0.000171	None.
30	20481702-030IM	20481702-030IM26A	Kitchen - Soda Machine Ice Maker (West)	6/18/2018	Passed with None Detected	None.
31	20481702-031IM	20481702-031IM26A	Kitchen - Pizza Area (West Side) - Ice Machine	6/18/2018	Passed with 0.000161	None.
32	20481702-032KF	20481702-032KF26A	Kitchen - Pizza Area (West Side) - Food Prep Sink	6/18/2018	Passed with 0.00191	None.
33	20481702-033KF	20481702-033KF26A	Kitchen - Pizza Area (West Side) - Hand Wash Sink	5/8/2019	Passed with 0.00292	None.
34	20481702-034DW	20481702-034DW26A	Cafeteria - Drinking Fountain (Upper)	6/29/2017	Passed with 0.00217	This DF was taken out of commission due to complaints of smells.
35	20481702-035DW	20481702-035DW26A	Cafeteria - Drinking Fountain (Lower)	6/29/2017	Passed with 0.00171	This DF was taken out of commission due to complaints of smells.
36	20481702-036BF	20481702-036BF26A	Cafeteria - Men's Restroom - Sink (Left)	5/8/2019	Passed with 0.00284	None.
37	20481702-037BF	20481702-037BF26A	Cafeteria - Men's Restroom - Sink (Center)	5/8/2019	Passed with 0.00415	None.
38	20481702-038BF	20481702-038BF26A	Cafeteria - Men's Restroom - Sink (Right)	5/8/2019	Passed with 0.00498	None.
39	20481702-039BF	20481702-039BF26A	Cafeteria - Women's Restroom - Sink (1)	5/8/2019	Passed with 0.00856	None.
40	20481702-040BF	20481702-040BF26A	Cafeteria - Women's Restroom - Sink (2)	8/20/2019	Passed with 0.00398	None.
41	20481702-041BF	20481702-041BF26A	Cafeteria - Women's Restroom - Sink (3)	5/8/2019	Passed with 0.00286	None.
42	20481702-042BF	20481702-042BF26A	Cafeteria - Women's Restroom - Sink (4)	5/8/2019	Passed with 0.00146	None.
43	20481702-043CF	20481702-043CF26A	Room C-1 - Sink	5/8/2019	Passed with 0.000299	None.
44	20481702-044BF	20481702-044BF26A	Room C-1 Staff Unisex Restroom - Sink	8/20/2019	Passed with 0.00712	None.

Lead Tests - North Medford High Gym - # 20481703

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481703-001WB	20481703-001WB26A	Main Gym Lobby - Bottle Filler (South)	6/18/2018	Passed with None 000130	This drinking fountain has a sediment filter on it.
2	20481703-002DW	20481703-002DW26A	Main Gym Lobby - Drinking Fountain (North)	5/6/2020	Passed with 0.00345	None.
3	20481703-003OT	20481703-003OT26A	Concession Stand - Sink	6/18/2018	Passed with 0.00370	This sink has a lead filter on it.
4	20481703-004OT	20481703-004OT26A	Concession Stand - Capuccino Machine	6/18/2018	Passed with 0.000692	The water supply for this machine has a lead filter on it.
5	20481703-005OT	20481703-005OT26A	Concession Stand - Coffee Machine	6/18/2018	Passed with 0.000168	The water supply for this machine has a lead filter on it.
6	20481703-006OT	20481703-006OT26A	Concession Stand - Soda Machine	6/18/2018	Passed with 0.000919	The water supply for this machine has a lead filter on it.
7	20481703-007DW	20481703-007DW26A	Main Gym - Drinking Fountain (East)	6/18/2018	Passed with 0.00284	None.
8	20481703-008DW	20481703-008DW26A	Main Gym - Drinking Fountain (West)	6/18/2018	Passed with 0.000809	None.
9	20481703-009BF	20481703-009BF26A	Near Main Gym Lobby Men's Restroom - Sink (Left)	5/8/2019	Passed with 0.000787	None.
10	20481703-010BF	20481703-010BF26A	Near Main Gym Lobby Men's Restroom - Sink (Center)	5/8/2019	Passed with 0.00122	None.
11	20481703-011BF	20481703-011BF26A	Near Main Gym Lobby Men's Restroom - Sink (Right)	5/8/2019	Passed with 0.00226	None.
12	20481703-012BF	20481703-012BF26A	Near Main Gym Lobby Women's Restroom - Sink (Left)	5/8/2019	Passed with 0.00243	None.
13	20481703-013BF	20481703-013BF26A	Near Main Gym Lobby Women's Restroom - Sink (Center)	5/8/2019	Passed with 0.00135	None.
14	20481703-014BF	20481703-014BF26A	Near Main Gym Lobby Women's Restroom - Sink (Right)	5/8/2019	Passed with 0.000957	None.
15	20481703-015DW	20481703-015DW26A	Girl's Locker Room - Drinking Fountain	6/18/2018	Passed with 0.00127	None.
16	20481703-016BF	20481703-016BF26A	Girl's Locker Room - Sink (RR)	8/28/2019	Passed with 0.00105	None.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (1)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (2)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (3)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (4)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (5)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (6)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (7)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (8)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (9)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (10)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (11)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (12)	N/A	N/A	Water should not be consumed from the shower head.

N/A	N/A	N/A	Girl's Locker Room - Shower Head (13)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (14)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (15)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (16)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (17)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (18)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (19)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (20)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (21)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (22)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (23)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (24)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (25)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (26)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (27)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (28)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (29)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Shower Head (30)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Girl's Locker Room - Coach's Rest Room - Shower	N/A	N/A	Water should not be consumed from the shower head.
17	20481703-017BF	20481703-017BF26A	Girl's Locker Room - Coach's Rest Room - Sink	8/28/2019	Passed with 0.00145	None.
18	20481703-018OT	20481703-018OT26A	Gym - Training Room - Sink	5/8/2019	Passed with 0.000830	None.
19	20481703-019IM	20481703-019IM26A	Gym - Training Room - Ice Machine	6/18/2018	Passed with 0.000292	None.
20	20481703-020OT	20481703-020OT26A	Gym - Training Room - Drinking Cooler Filler Hose	6/18/2018	Passed with 0.00584	This hose has a lead filter on it.
21	20481703-021DW	20481703-021DW26A	Boy's Locker Room - Drinking Fountain (Locker Area - West)	6/18/2018	Passed with 0.00130	None.
22	20481703-022DW	20481703-022DW26A	Boy's Locker Room - Drinking Fountain (RR Area - East)	6/18/2018	Passed with 0.00121	None.
23	20481703-023SF	20481703-023SF26A	Boy's Locker Room Coach's Lounge - Sink	8/28/2019	Passed with 0.000540	None.
24	20481703-024BF	20481703-024BF26A	Boy's Locker Room - Sink (Left)	5/8/2019	Passed with 0.00473	None.
25	20481703-025BF	20481703-025BF26A	Boy's Locker Room - Sink (Right)	5/8/2019	Passed with 0.00411	None.
26	20481703-026BF	20481703-026BF26A	Locker Room Hallway Unisex Rest Room - Sink	5/8/2019	Passed with 0.00389	None.
27	20481703-027BF	20481703-027BF26A	Boy's Locker Room - Coach's Rest Room - Sink	5/8/2019	Passed with 0.00279	None.
28	20481703-028DW	20481703-028DW26A	Outside Wrestling Room - Drinking Fountain	6/18/2018	Passed with 0.00295	None.
29	20481703-029DW	20481703-029DW26A	Upper Gym - Drinking Fountain	6/18/2018	Passed with 0.00141	None.
N/A	N/A	N/A	Boy's Locker Room - Shower Head (1)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Boy's Locker Room - Shower Head (2)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Boy's Locker Room - Shower Head (3)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Boy's Locker Room - Shower Head (4)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Boy's Locker Room - Shower Head (5)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Boy's Locker Room - Shower Head (6)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Boy's Locker Room - Shower Head (7)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Boy's Locker Room - Shower Head (8)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Boy's Locker Room - Shower Head (9)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Boy's Locker Room - Shower Head (10)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Boy's Locker Room - Shower Head (11)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Boy's Locker Room - Shower Head (12)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Boy's Locker Room - Shower Head (13)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Boy's Locker Room - Shower Head (14)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Boy's Locker Room - Shower Head (15)	N/A	N/A	Water should not be consumed from the shower head.
N/A	N/A	N/A	Boy's Locker Room - Coach's Rest Room - Shower	5/8/2019	Passed with 0.00100	Water should not be consumed from the shower head.
Lead Tests - North Medford High Science Building - # 20481704						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481704-001DW	20481704-001DW26A	Outside S-6 - Drinking Fountain	5/6/2020	Passed with 0.00373	This drinking fountain has a lead filter on it.
2	20481704-002DW	20481704-002DW26A	Outside Planatarium - Drinking Fountain	6/18/2018	Passed with 0.00276	None.
3	20481704-003BF	20481704-003BF26A	Outside Planatarium Men's Restroom - Sink (Left)	5/2/2019	Passed with 0.000745	None.
4	20481704-004BF	20481704-004BF26A	Outside Planatarium Men's Restroom - Sink (Center)	5/2/2019	Passed with 0.00204	None.
5	20481704-005BF	20481704-005BF26A	Outside Planatarium Men's Restroom - Sink (Right)	5/2/2019	Passed with 0.00212	None.
6	20481704-006BF	20481704-006BF26A	Outside Planatarium Women's Restroom - Sink (Left)	5/2/2019	Passed with 0.00318	None.
7	20481704-007BF	20481704-007BF26A	Outside Planatarium Women's Restroom - Sink (Center)	5/2/2019	Passed with 0.000848	None.
8	20481704-008BF	20481704-008BF26A	Outside Planatarium Women's Restroom - Sink (Right)	5/2/2019	Passed with 0.00282	None.
9	20481704-009DW	20481704-009DW26A	Outside S4 - Drinking Fountain	6/18/2018	Passed with 0.000421	This drinking fountain has a lead filter on it.
10	20481704-010BF	20481704-010BF26A	Outside S2 Men's Restroom - Sink	5/2/2019	Passed with 0.00101	None.
11	20481704-011BF	20481704-011BF26A	Outside S2 Women's Restroom - Sink	5/2/2019	Passed with 0.00399	None.
N/A	N/A	N/A	S-8 - Sink (1 - With Eye Wash)	N/A	N/A	Water should not be consumed from the eye wash.
N/A	N/A	N/A	S-8 - Sink (2)	N/A	N/A	"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-8 - Sink (3)	N/A	N/A	"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-8 - Sink (4)	N/A	N/A	"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-8 - Sink (5)	N/A	N/A	"Non-Potable Water" Sign Installed 12 Dec 2019.

N/A	N/A	N/A	S-2 - Sink (4)	N/A	N/A	"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-2 - Sink (5)	N/A	N/A	"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-2 - Sink (6)	N/A	N/A	"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-2 - Sink (7)	N/A	N/A	"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Island Sink	N/A	N/A	"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Sink (1)	N/A	N/A	"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Sink (2)	N/A	N/A	"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Sink (3)	N/A	N/A	"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Sink (3 - Eye Wash)	N/A	N/A	"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Sink (4)	N/A	N/A	"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Sink (5)	N/A	N/A	"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Sink (6)	N/A	N/A	"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Sink (7)	N/A	N/A	"Non-Potable Water" Sign Installed 12 Dec 2019.
Lead Tests - North Medford High Observatory - # 20481705						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
N/A						
No Fixtures in this building						
Lead Tests - North Medford High Technical Arts 1-10 Building - # 20481706						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481706-001CF	20481706-001CF26A	TA-10 - Trough Sink (Fixture 1)	5/8/2019	Passed with 0.00302	None.
2	20481706-002CF	20481706-002CF26A	TA-10 - Trough Sink (Fixture 2)	5/8/2019	Passed with 0.00125	None.
3	20481706-003CF	20481706-003CF26A	TA-10 - Trough Sink (Fixture 3)	5/8/2019	Passed with 0.000575	None.
4	20481706-004CF	20481706-004CF26A	TA-10 - Trough Sink (Fixture 4)	5/8/2019	Passed with 0.00503	None.
5	20481706-005DW	20481706-005DW26A	TA-10 - Drinking Fountain	5/6/2020	Passed with 0.00342	None.
6	20481706-006BF	20481706-006BF26A	Outside TA-9 Girl's Restroom - Sink (1)	5/8/2019	Passed with 0.00446	None.
7	20481706-007BF	20481706-007BF26A	Outside TA-9 Girl's Restroom - Sink (2)	5/8/2019	Passed with 0.00314	None.
8	20481706-008BF	20481706-008BF26A	Outside TA-9 Girl's Restroom - Sink (3)	5/8/2019	Passed with 0.00309	None.
9	20481706-009BF	20481706-009BF26A	Outside TA-9 Girl's Restroom - Sink (4)	5/8/2019	Passed with 0.00200	None.
10	20481706-010CF	20481706-010CF26A	TA-9 - Trough Sink (Fixture 1)	5/8/2019	Passed with 0.00378	None.
11	20481706-011CF	20481706-011CF26A	TA-9 - Trough Sink (Fixture 2)	5/8/2019	Passed with 0.00670	None.
12	20481706-012CF	20481706-012CF26A	TA-9 - Trough Sink (Fixture 3)	5/8/2019	Passed with 0.00173	None.
13	20481706-013CF	20481706-013CF26A	TA-9 - Trough Sink (Fixture 4)	5/8/2019	Passed with 0.00354	None.
14	20481706-014CF	20481706-014CF26A	TA-9 - Trough Sink (Fixture 5)	5/8/2019	Passed with 0.00387	None.
15	20481706-015DW	20481706-015DW26A	TA-9 - Drinking Fountain	6/18/2018	Passed with 0.000916	None.
N/A	N/A	N/A	TA-9 - Eye Wash	N/A	N/A	Water should not be consumed from the eye wash.
16	20481706-016BF	20481706-016BF26A	Adjacent To TA-1 Men's Restroom - Sink (1)	5/8/2019	Passed with 0.00329	None.
17	20481706-017BF	20481706-017BF26A	Adjacent To TA-1 Men's Restroom - Sink (2)	5/8/2019	Passed with 0.00373	None.
18	20481706-018BF	20481706-018BF26A	Adjacent To TA-1 Men's Restroom - Sink (3)	5/8/2019	Passed with 0.00681	None.
19	20481706-019BF	20481706-019BF26A	Adjacent To TA-1 Men's Restroom - Sink (4)	5/8/2019	Passed with 0.00340	None.
20	20481706-020CF	20481706-020CF26A	TA-8 - Sink	5/8/2019	Passed with 0.00159	None.
21	20481706-021CF	20481706-021CF26A	TA-8 - Sink (Utility)	5/8/2019	Passed with 0.00129	None.
22	20481706-022CF	20481706-022CF26A	TA-7 - Sink	5/8/2019	Passed with 0.00230	None.
23	20481706-023DW	20481706-023DW26A	Outside TA-1 - Drinking Fountain (Upper)	6/18/2018	Passed with 0.00176	This drinking fountain has a lead filter on it.
24	20481706-024DW	20481706-024DW26A	Outside TA-1 - Drinking Fountain (Lower)	6/18/2018	Passed with 0.000947	This drinking fountain has a lead filter on it.
25	20481706-025CF	20481706-025CF26A	TA-5 - Sink (1)	5/8/2019	Passed with 0.00273	None.
26	20481706-026CF	20481706-026CF26A	TA-5 - Sink (2)	5/8/2019	Passed with 0.00195	None.
27	20481706-027CF	20481706-027CF26A	TA-5 - Sink (3)	5/8/2019	Passed with 0.00217	None.
28	20481706-028CF	20481706-028CF26A	TA-5 - Sink (4)	5/8/2019	Passed with 0.00305	None.
29	20481706-029CF	20481706-029CF26A	TA-5 - Sink (5)	5/8/2019	Passed with 0.00408	None.
30	20481706-030CF	20481706-030CF26A	TA-5 - Sink (6)	5/8/2019	Passed with 0.00133	None.
31	20481706-031CF	20481706-031CF26A	TA-5 - Sink (7)	5/8/2019	Passed with 0.00471	None.
32	20481706-032CF	20481706-032CF26A	TA-5 - Sink (Island)	5/8/2019	Passed with 0.00752	None.
33	20481706-033SF	20481706-033SF26A	Inbetween TA-5/6 - Sink (West)	5/8/2019	Passed with 0.00112	None.
N/A	N/A	N/A	Inbetween TA-5/6 (Science) - Sink (East)	5/8/2019	Passed with 0.0101	"Not For Consumption" Sign Installed 24 July 2019.
N/A	N/A	N/A	Inbetween TA-5/6 - Eyewash	N/A	N/A	Water should not be consumed from the eye wash.
34	20481706-034CF	20481706-034CF26A	TA-6 - Sink (1)	5/8/2019	Passed with 0.00121	None.
35	20481706-035CF	20481706-035CF26A	TA-6 - Sink (2)	5/8/2019	Passed with 0.000864	None.
36	20481706-036CF	20481706-036CF26A	TA-6 - Sink (3)	5/8/2019	Passed with 0.00242	None.
37	20481706-037CF	20481706-037CF26A	TA-6 - Sink (4)	5/8/2019	Passed with 0.00199	None.
38	20481706-038CF	20481706-038CF26A	TA-6 - Sink (5)	5/8/2019	Passed with 0.000798	None.
39	20481706-039CF	20481706-039CF26A	TA-6 - Sink (6)	5/8/2019	Passed with 0.00285	None.
40	20481706-040CF	20481706-040CF26A	TA-6 - Sink (7)	5/8/2019	Passed with 0.00233	None.
41	20481706-041CF	20481706-041CF26A	TA-6 - Sink (Island)	5/8/2019	Passed with 0.00483	None.
Lead Tests - North Medford High Technical Arts 11-12 Building - # 20481707						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481707-001DW	20481707-001DW26A	TA-11 - Drinking Fountain	6/18/2018	Passed with 0.000773	None.
2	20481707-002CF	20481707-002CF26A	TA-11 - Sink	5/8/2019	Passed with 0.00702	None.

3	20481707-003DW	20481707-003DW26A	TA-12 - Drinking Fountain	6/18/2018	Passed with 0.00942	None.
4	20481707-004CF	20481707-004CF26A	TA-12 - Sink	8/20/2019	Passed with 0.000438	None.
5	20481707-005BF	20481707-005BF26A	Outside TA-11 Men's Restroom - Sink	1/23/2020	Passed with 0.000110	This fixture has a lead filter on it.
6	20481707-006BF	20481707-006BF26A	Outside TA-11 Women's Restroom - Sink	8/20/2019	Passed with 0.00117	None.

Lead Tests - North Medford High Child Development Center - # 20481708

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481708-001KF	20481708-001KF26A	CDC - Kitchen - Sink	6/18/2018	Passed with 0.000599	None.
2	20481708-002SF	20481708-002SF26A	CDC - Infant Area - Sink (Immediately Outside Kitchen Door)	6/18/2018	Passed with 0.000612	None.
3	20481708-003SF	20481708-003SF26A	CDC - Toddler Area - Sink (Left)	6/18/2018	Passed with 0.00136	None.
4	20481708-004SF	20481708-004SF26A	CDC - Toddler Area - Sink (Right)	6/18/2018	Passed with 0.00108	None.
5	20481708-005SF	20481708-005SF26A	CDC - Toddler Hallway Near Washer/Dryer - Sink (Left)	7/9/2018	Passed with 0.000957	None.
6	20481708-006SF	20481708-006SF26A	CDC - Toddler Hallway Near Washer/Dryer - Sink (Right)	6/18/2018	Passed with 0.00219	None.
7	20481708-007BF	20481708-007BF26A	CDC - Toddler Unisex Restroom - Sink	5/8/2019	Passed with 0.000304	None.
8	20481708-008BF	20481708-008BF26A	CDC - Pre-School Unisex Restroom - Sink (Left)	5/8/2019	Passed with 0.000786	None.
9	20481708-009BF	20481708-009BF26A	CDC - Pre-School Unisex Restroom - Sink (Right)	5/8/2019	Passed with 0.00113	None.
10	20481708-010DW	20481708-010DW26A	CDC - Pre-School Classroom 1 - Drinking Fountain	5/6/2020	Passed with 0.000792	None.
11	20481708-011CF	20481708-011CF26A	CDC - Pre-School Classroom 1 - Sink	6/18/2018	Passed with 0.00253	None.
12	20481708-012CF	20481708-012CF26A	CDC - Pre-School Classroom 2 - Sink	6/18/2018	Passed with 0.00378	None.
13	20481708-013DW	20481708-013DW26A	CDC - Pre-School Playground - Drinking Fountain (Outside)	6/18/2018	Passed with 0.00148	This drinking fountain has a lead filter on it.

Lead Tests - North Medford High Health - Culinary Building - # 20481709

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481709-001CF	20481709-001CF26A	HC-8 - Sink	6/18/2018	Passed with 0.00308	None.
2	20481709-002IM	20481709-002IM26A	HC-6 - Ice-o-matic	6/18/2018	Passed with 0.00147	This ice machine has a lead filter on it.
3	20481709-003CF	20481709-003CF26A	HC-6 - Island Sink Triple (Left Fixture)	5/6/2020	Passed with 0.00232	None.
4	20481709-004CF	20481709-004CF26A	HC-6 - Island Sink Triple (Right Fixture)	6/18/2018	Passed with 0.00692	None.
5	20481709-005CF	20481709-005CF26A	HC-6 - Hand Wash - Sink	5/8/2019	Passed with 0.00161	None.
6	20481709-006CF	20481709-006CF26A	HC-7 - Sink (1)	6/18/2018	Passed with 0.000585	None.
7	20481709-007CF	20481709-007CF26A	HC-7 - Sink (2)	6/18/2018	Passed with 0.00152	None.
8	20481709-008CF	20481709-008CF26A	HC-7 - Sink (3)	6/18/2018	Passed with 0.00403	None.
9	20481709-009CF	20481709-009CF26A	HC-7 - Sink (4)	6/18/2018	Passed with 0.00375	None.
10	20481709-010CF	20481709-010CF26A	HC-7 - Sink (5)	6/18/2018	Passed with 0.00264	None.
11	20481709-011CF	20481709-011CF26A	HC-7 - Sink (6)	6/18/2018	Passed with 0.00184	None.
12	20481709-012CF	20481709-012CF26A	HC-7 - Sink (7)	6/18/2018	Passed with 0.00317	None.
13	20481709-013CF	20481709-013CF26A	HC-7 - Sink (8)	6/18/2018	Passed with 0.00154	None.
14	20481709-014CF	20481709-014CF26A	HC-5 - Sink	8/20/2019	Passed with 0.000568	None.
15	20481709-015CF	20481709-015CF26A	HC-4 - Sink	6/18/2018	Passed with 0.00931	None.
16	20481709-016DW	20481709-016DW26A	Across From HC-4 - Drinking Fountain	5/6/2020	Passed with 0.00163	None.
17	20481709-017BF	20481709-017BF26A	HC Women's Restroom - Sink (Left)	9/10/2019	Passed with 0.00245	None.
18	20481709-018BF	20481709-018BF26A	HC Women's Restroom - Sink (Center)	5/8/2019	Passed with 0.000458	None.
19	20481709-019BF	20481709-019BF26A	HC Women's Restroom - Sink (Right)	5/8/2019	Passed with 0.00195	None.
20	20481709-020BF	20481709-020BF26A	HC Men's Restroom - Sink (1)	5/8/2019	Passed with None Detected	None.
21	20481709-021BF	20481709-021BF26A	HC Men's Restroom - Sink (2)	5/8/2019	Passed with None Detected	None.
22	20481709-022BF	20481709-022BF26A	HC Men's Restroom - Sink (3)	5/8/2019	Passed with None Detected	None.
23	20481709-023BF	20481709-023BF26A	HC Men's Restroom - Sink (4)	5/8/2019	Passed with None Detected	None.
24	20481709-024CF	20481709-024CF26A	HC-3 - Sink	5/8/2019	Passed with 0.00129	None.
25	20481709-027BF	20481709-027BF26A	HC - Staff Restroom - Sink	5/8/2019	Passed with 0.000163	None.
N/A	N/A	N/A	HC-2 - Sink (1)	6/18/2018	Passed with 0.000158	This sink was removed as part of the CTE classroom construction.
N/A	N/A	N/A	HC-2 - Sink (2)	6/18/2018	Passed with None Detected	This sink was removed as part of the CTE classroom construction.
N/A	N/A	N/A	HC-2 - Sink (3)	6/18/2018	Passed with 0.000169	This sink was removed as part of the CTE classroom construction.
N/A	N/A	N/A	HC-2 - Sink (4)	6/18/2018	Passed with None Detected	This sink was removed as part of the CTE classroom construction.
N/A	N/A	N/A	HC-2 - Sink (5)	6/18/2018	Passed with 0.000168	This sink was removed as part of the CTE classroom construction.
N/A	N/A	N/A	HC-2 - Sink (6)	6/18/2018	Passed with 0.00191	This sink was removed as part of the CTE classroom construction.
N/A	N/A	N/A	HC-2 - Sink (7)	6/18/2018	Passed with 0.00276	This sink was removed as part of the CTE classroom construction.

Lead Tests - North Medford High Humanities Building - # 20481710

#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481710-001DW	20481710-001DW26A	Outside H-21 - Drinking Fountain	6/18/2018	Passed with 0.00102	None.
2	20481710-002DW	20481710-002DW26A	Outside H-13 - Drinking Fountain	5/6/2020	Passed with 0.00266	None.
3	20481710-003BF	20481710-003BF26A	Outside H-9 Women's Restroom - Sink	5/8/2019	Passed with 0.000405	None.
4	20481710-004BF	20481710-004BF26A	Outside H-4 Men's Restroom - Sink	5/8/2019	Passed with 0.00151	None.
5	20481710-005BF	20481710-005BF26A	Across From H-38 Men's Restroom - Sink (1)	5/8/2019	Passed with 0.00259	None.
6	20481710-006BF	20481710-006BF26A	Across From H-38 Men's Restroom - Sink (2)	5/8/2019	Passed with 0.000391	None.
7	20481710-007BF	20481710-007BF26A	Across From H-38 Men's Restroom - Sink (3)	5/8/2019	Passed with 0.000537	None.
8	20481710-008BF	20481710-008BF26A	Across From H-38 Men's Restroom - Sink (4)	5/8/2019	Passed with 0.000620	None.
9	20481710-009BF	20481710-009BF26A	Across From H-38 Men's Restroom - Sink (5)	5/8/2019	Passed with 0.00108	None.
10	20481710-010BF	20481710-010BF26A	Across From H-38 Men's Restroom - Sink (6)	5/8/2019	Passed with 0.00495	None.
11	20481710-011BF	20481710-011BF26A	Across From H-38 Men's Restroom - Sink (7)	5/8/2019	Passed with 0.00114	None.

12	20481710-012BF	20481710-012BF26A	Across From H-38 Men's Restroom - Sink (8)	5/8/2019	Passed with 0.000877	None.
13	20481710-013BF	20481710-013BF26A	Across From H-38 Women's Restroom - Sink (1)	5/8/2019	Passed with 0.000304	None.
14	20481710-014BF	20481710-014BF26A	Across From H-38 Women's Restroom - Sink (2)	5/8/2019	Passed with 0.000342	None.
15	20481710-015BF	20481710-015BF26A	Across From H-38 Women's Restroom - Sink (3)	5/8/2019	Passed with 0.00114	None.
16	20481710-016BF	20481710-016BF26A	Across From H-38 Women's Restroom - Sink (4)	5/8/2019	Passed with 0.000581	None.
17	20481710-017BF	20481710-017BF26A	Across From H-38 Women's Restroom - Sink (5)	5/8/2019	Passed with 0.00117	None.
18	20481710-018BF	20481710-018BF26A	Across From H-38 Women's Restroom - Sink (6)	5/8/2019	Passed with 0.000434	None.
19	20481710-019BF	20481710-019BF26A	Across From H-38 Women's Restroom - Sink (7)	5/8/2019	Passed with 0.000413	None.
20	20481710-020BF	20481710-020BF26A	Across From H-38 Women's Restroom - Sink (8)	5/8/2019	Passed with 0.000294	None.
21	20481710-021DW	20481710-021DW26A	Outside H-38 - Drinking Fountain (Left Fixture)	6/18/2018	Passed with 0.00271	None.
22	20481710-022DW	20481710-022DW26A	Outside H-38 - Drinking Fountain (Right Fixture)	6/18/2018	Passed with 0.000460	None.
Lead Tests - North Medford High Media Center - Commons Building - # 20481711						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481711-001BF	20481711-001BF26A	Common's Men's Restroom - Sink (Left)	5/8/2019	Passed with 0.000927	None.
2	20481711-002BF	20481711-002BF26A	Common's Men's Restroom - Sink (Center)	5/8/2019	Passed with 0.000530	None.
3	20481711-003BF	20481711-003BF26A	Common's Men's Restroom - Sink (Right)	5/8/2019	Passed with 0.000762	None.
4	20481711-004BF	20481711-004BF26A	Common's Women's Restroom - Sink (Left)	5/8/2019	Passed with 0.00135	None.
5	20481711-005BF	20481711-005BF26A	Common's Women's Restroom - Sink (Center)	5/8/2019	Passed with 0.00101	None.
6	20481711-006BF	20481711-006BF26A	Common's Women's Restroom - Sink (Right)	5/8/2019	Passed with 0.000582	None.
7	20481711-007DW	20481711-007DW26A	Common's - Drinking Fountain (Upper - Bottle Filler)	6/18/2018	Passed with None Detected	This drinking fountain has a sediment filter on it.
8	20481711-008DW	20481711-008DW26A	Common's - Drinking Fountain (Lower)	6/18/2018	Passed with 0.000623	None.
9	20481711-009SF	20481711-009SF26A	Common's - Sink (South West Corner)	6/18/2018	Passed with 0.000184	None.
10	20481711-010SF	20481711-010SF26A	Common's - Sink (South East Corner)	6/18/2018	Passed with 0.000900	None.
11	20481711-011BF	20481711-011BF26A	Media Center Staff Unisex Restroom - Sink	5/8/2019	Passed with 0.000972	None.
12	20481711-012SF	20481711-012SF26A	Media Center Work Room - Sink	5/8/2019	Passed with 0.000724	None.
Lead Tests - North Medford High Tennis Court - # 20481712						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481712-001DW	20481712-001DW26A	Tennis Court - Drinking Fountain	6/18/2018	Passed with 0.00144	None.
2	20481712-002DW	20481712-002DW26A	JV Softball Field - Drinking Fountain (Behind Backstop)	6/18/2018	Passed with 0.00586	None.
Lead Tests - North Medford High Varsity Baseball Building - # 20481713						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481713-001DW	20481713-001DW26A	Baseball Field - Drinking Fountain (Visitors Dugout)	6/18/2018	Passed with 0.00986	None.
2	20481713-002OT	20481713-002OT26A	Baseball Field - Concession Stand - Soda Machine	7/29/2016	Passed with 0.00146	Seth did not see a soda machine. This machine currently has no water sup
3	20481713-003IM	20481713-003IM26A	Baseball Field - Concession Stand - Ice Machine	6/18/2018	Passed with None Detected	None.
4	20481713-004BF	20481713-004BF26A	Baseball Field - Men's Restroom - Sink	5/8/2019	Passed with 0.00378	None.
5	20481713-005BF	20481713-005BF26A	Baseball Field - Women's Restroom - Sink	5/8/2019	Passed with 0.00478	None.
6	20481713-006DW	20481713-006DW26A	Baseball Field - Outside Restrooms - Drinking Fountain	6/18/2018	Passed with 0.00146	None.
Lead Tests - North Medford High Track Building - # 20481714						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481714-001IM	20481714-001IM26A	Bowerman Concession Stand - Ice Machine	6/18/2018	Passed with 0.000226	None.
2	20481714-002OT	20481714-002OT26A	Bowerman Concession Stand - Sink	6/18/2018	Passed with 0.00576	None.
3	20481714-003DW	20481714-003DW26A	Outside Bowerman Concession Stand - Drinking Fountain	6/18/2018	Passed with 0.00830	None.
Lead Tests - North Medford High Bathrooms Near (SW) - Track Building - # 20481715						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481715-001BF	20481715-001BF26A	Near Track Men's Restroom (South East) - Sink	5/8/2019	Passed with 0.00546	None.
2	20481715-002BF	20481715-002BF26A	Near Track Men's Restroom (North East) - Sink	5/8/2019	Passed with 0.00364	None.
3	20481715-003BF	20481715-003BF26A	Near Track Unisex Restroom (South West) - Sink	5/8/2019	Passed with 0.00405	None.
4	20481715-004BF	20481715-004BF26A	Near Track Unisex Restroom (North West) - Sink	5/8/2019	Passed with 0.00289	None.
NA	N/A	N/A	Near Track Training Room (Spa In It) - Sink (Utility)	8/20/2019	Passed with 0.000384	Converted to custodial sink
5	20481715-005OS	20481715-005OS26A	Water Horse # 1 (West)	6/18/2018	Passed with 0.0131	
6	20481715-006OS	20481715-006OS26A	Water Horse # 2 (East)	6/18/2018	Passed with 0.000674	

*None Detected (ND) = .005 Or Less

 = Fixture Where Water Has The Potential of Being Consumed (All of These Will Be Tested When Testing The Whole School)

*ODE's required action level is 15 parts per billion (PPB)

*The E.P.A.'s recommended action level for lead in schools is 0.020. Oregon's action level for schools changed to 0.015 in 2019 in accordance with OAR 333-061-0400. In 2021, ODE changed the unit of measurement for reporting to parts per billion (PPB)

*The E.P.A. action level for copper is 1.30

*Lead test results will be posted on the MSD/Facilities website within 5 days minus the school map for security purposes.